

Padova



1 x1



2 x1



3 x1



4 x2



5 x3



6 x4



7 x4



8 x8



9 x8



10 x4



11 x4



12 x5



13 x5



14 x5



15 x5



16 x4



Istruzioni



Fasi



1 x1



2 x1



3 x1



5 x3



6 x4



8 x8



9 x4




11 x4




16 x4

1



2



3

